

2020 OTHER TOYOTA TUNDRA CREWMAX SR5



Asset Detail

VIN	5TFEY5F16LX258613
STOCK #	NA
LOT #	48386810
PO #	NA
YEAR	2020
MAKE	OTHER
MODEL	TOYOTA TUNDRA CREWMAX SR5
TYPE	LightDuty ()

Asset Specifications

OD MILES	6336	ENG MAKE	Toyota
ENG DETAIL	5.7L 8	ENG HP	346
FUEL TYPE	Gasoline	FUEL TANKS	1
FUEL CAPAC	26	TRANS SPD.	6
TRANS TYPE	Auto	CRUISE	Yes
PWR STEER	Yes	AXLE TYPE	Single
AXLE F	3900	AXLE R	4150
GVW	7000	SUSPENSION	Shock / Spring
LIFT GATE?	No	WHEELBASE	145
TIRE SIZE R	275/55R20	TIRE SIZE F	275/55R20
WHEEL F	Alloy	WHEEL R	Alloy
AIR COND	Yes	AIR COND OPERABLE	Yes
INT COLOR	Black	RADIO	AM/FM
RADIO OPERABLE	Yes	POWER MIRRORS	Dual Power
HIGH BACK SEATS	Dual	EXT COLOR	Blue
BUMPER	Chrome		

Brakes

FL

/ 32

/ 32

FR

BRAKE TYPE: NA

RL 1

/ 32

/ 32

RR 1

Tires & Wheels

FL

15 / 32
Goodyear
Cast

15 / 32
Goodyear
Cast

FR

FRONT: 275/55R20

REAR: 275/55R20

RL01

15 / 32
Goodyear
Cast

RLi1

/ 32

/ 32

RRi1

15 / 32
Goodyear
Cast

RRo1

General Observations

Oil Leaks: **No** Oil Milky: **No** Water Leaks: **No** Oil in Coolant: **No** Starts: **Yes** Runs/Drives: **Yes**

Safety Observations

Exterior Lights Operable: **Yes - All** Wipers Operable: **Yes - All** Guages Operable: **Yes - All**
City Horn Operable: **Yes - All** Air Horn Operable: **NA**




INSPECTION #12069 11/04/2020

PREPARED FOR
CREDIT CARD-COPART CLIENTS
Copart - TX - Fort Worth
[HASLET, TX](#)

Wear & Tear Observations	
Rear frame	Bent on both sides
Rear bumper	Needs replaced
Bed	Damage to front of bed next to cab
Cab	Rear left side damage
Hitch	Needs replaced
Tailgate	Scratches and dents







Condition report only.

Advantage Equipment Inspections does not guarantee mechanical reliability.

© 2020 Advantage Equipment Inspections
908 NW Vesper Street Blue Springs, MO 64015
(816) 220-1146